205 EPI

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 783 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL - U.S. OFFICIALS ONLY SECURITY INFORMATION

COUNTRY	Poland	REPORT		25X1
SUBJECT	Furnace Breakdowns and Defective Castings at Stalowa Wola Foundry	DATE DISTR.	6 October 19	953
DATE OF INFO.		REQUIREMENT NO.	RD	25X1
PLACE ACQUIRED	This is UNEVALUATED Information	REFERENCES		
	THE SOURCE EVALUATIONS IN THIS REPORT THE APPRAISAL OF CONTENT IS T (FOR KEY SEE REVERSE)			
				25X1

- The two Martin furnaces which were only recently put into action at the Stalowa Wola Foundry have had to undergo general repairs. The stays (trsony) are correded and the covering and walls have caved in. The reason for this was defective fireproof material.
- 2. The trials for the casting of gun tubes by the German facilities for the production of centrifugally cast gun tubes have failed. Two guns were cast. One split and the other showed signs of cracks. Both these guns are to be given thermal treatment, but they will not be disposed of on the open market.

25 YEAR RE-REVIEW

SECRET/CONTROL - U.S. OFFICIALS ONLY

STATE	x	ARMY	x	NAVY	x	AIR	x	FB1	 AEC		T	

Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)